

## Cheat Sheet for Hadar's Quick-fire Clays

	<b>Color</b>	<b>Uses</b>	<b>Schedule</b>	<b>Shrinkage</b>	<b>Pre-firing</b>
Copper	Red	On its own	High-fire	28%	Yes
		Combined with bronze or Brilliant Bronze;	Mid-fire	10%	Yes
		Combined with steel and/or Bronze <i>XT</i>	High-fire	28%	No
Bronze	Yellow	On its own	Mid-fire	15%	Yes
		Combined with copper and small accents of steel	Mid-fire	15%	Yes
Brilliant Bronze	Gold	On its own	Mid-fire	23.5%	Yes
		Combined with copper and small accents of steel	Mid-fire	23.5%	Yes
Bronze <i>XT</i>	Dark bronze	On its own	High-fire	15%	Yes
		Combined with copper and Low-shrinkage steel <i>XT</i>	High-fire	15%	No
Rose Bronze	Pink	On its own	High-fire	28%	Yes
		Combined with steels	Mid-fire	10%	Yes
			High-fire	28%	Yes
Low-shrinkage Steel <i>XT</i>	Gray	On its own	High-fire	28%	No
		Combined as the major ingredient with copper and/or Bronze <i>XT</i>	High-fire	28%	No
		Small accents combined with bronze and/or copper	Mid-fire	Low	Yes
Other steels	Black	Small accents combined with copper and bronze; patterns of color	Mid-fire	Low	Yes
White Bronze	Silver	On its own	Low fire	10%	No
		Added to other metals at second firing	Low-fire	10%	No